


SREEROSH LAURELS PROGRESS REPORT MARCH 2025



TERRACE FLOOR	100%	100%	100%	100%	100%	100%	100%
13TH FLOOR	100%	100%	100%	100%	100%	100%	100%
12th FLOOR	100%	100%	100%	100%	100%	100%	100%
11th FLOOR	100%	100%	100%	100%	100%	100%	100%
10th FLOOR	100%	100%	100%	100%	100%	100%	100%
9th FLOOR	100%	100%	100%	100%	100%	100%	100%
8th FLOOR	100%	100%	100%	100%	100%	100%	100%
7th FLOOR	100%	100%	100%	100%	100%	100%	100%
6th FLOOR	100%	100%	100%	100%	100%	100%	100%
5TH FLOOR	100%	100%	100%	100%	100%	100%	100%
4TH FLOOR	100%	100%	100%	100%	100%	100%	100%
3RD FLOOR	100%	100%	100%	100%	100%	100%	100%
2ND FLOOR	100%	100%	100%	100%	100%	100%	100%
1ST FLOOR	100%	100%	100%	100%	90%	100%	100%
GROUND FLOOR	100%	100%	100%	75% 30%			
BASEMENT	100%	95%	90%	50%			
SUBSTRUCTURE	100%						

PROJECT AT GLANCE

RCC ■ CEILING PLASTERING ■ MASONRY ■ WALL CHASING ■ WALL PLASTERING ■ PLUMBING ■ WATERPROOFING



PROGRESS PHOTOS



North West & South Elevation





Toilet daddoing

Apartment flooring





Joint filling & floor protection

Carpentry





Passage and Staircase putty & primer work

Apartment putty works






Duct doors

UPVC window frame work





HT electrical work

Fire fighting work

THANK YOU